

Diag. Code 16**ECT Control Signal Malfunction****— CIRCUIT DESCRIPTION —**

The signal from the ECT CPU retards the ignition timing of the engine during ECT gear shifting, thus momentarily reducing torque output of the engine for smooth clutch operation inside the transmission and reduced shift shock.

Code No.	Diagnostic Code Detecting Condition	Trouble Area
16	Fault in communications between the engine CPU and ECT CPU in the ECU.	•ECU

If the ECU records the diagnostic code “16” in memory, it prohibits the torque control of the ECT which performs smooth gear shifting.

— DIAGNOSTIC CHART —