


ABS & HYDRAULIC BRAKE BOOSTER POWER SUPPLY SYSTEM

DI284-14

HOW TO PROCEED WITH TROUBLESHOOTING

Troubleshooting in accordance with the procedure on the following pages.



Fail safe function:

When a failure occurs in the ABS system, the ABS warning light is lit and the ABS & BA & TRAC & VSC operation is prohibited.