

## 21. GPS mark does not appear.

### INSPECTION PROCEDURE

- |   |  |
|---|--|
| 1 | Check the mark display. (At a place with a fine view, is GPS mark displayed or not?) |
|---|--|

Yes

Normal.

No

- |   |   |
|---|---|
| 2 | Is there anything such as a film stuck to the window or any metal object on the instrument panel? |
|---|---|

Yes

Reception may be affected by a screen such as a film.

No

- |   |  |
|---|--|
| 3 | Check if the harness is caught or sharply bent or not. |
|---|--|

NG

Navigation antenna is surely connected.

OK

- |   |  |
|---|--|
| 4 | Check optional components. (Does it become normal if the optionals such as the theft deterrent system is removed?) |
|---|--|

Yes

Remove or change the position of the components.

#### HINT:

Some optionals receive radio signals, and if this happens, GPS reception may be affected.

No

<b>5</b>	<b>Is there anything such as a film stuck to the window?</b>
----------	--

**Yes****Reception may be affected by a screen such as a film.****No**

<b>6</b>	<b>Service check mode. (Is "80-40, 41" is displayed in the unit check mode of the navigation ECU?)</b>
----------	--

**Yes****Troubleshoot for each diagnosis.****No****Replace the navigation antenna.****HINT:**

If the trouble still occurs, replace the navigation ECU.