


SUSPENSION - FRONT

Fig. 3: Exploded View of Steering Knuckle (LS400)
Courtesy Of Courtesy of Toyota Motor Sales, U.S.A., Inc
1990 Lexus LS 400
For Lextreme

Copyright © 1998 Mitchell Repair Information Company, LLC
Thursday, January 29, 2004 04:57PM



91G02097