


## PRECHECK TYPE 2

Perform this check in cases where the wireless door lock control system fails to operate anywhere.



\*1 Performing lock and unlock once counts as one time.

\*2 In some localities, inspection cannot be carried out because the local radio broadcast is also at 94.9 MHz. When this occurs, perform inspection using a portable radio in a place indoors free from the influence of FM broadcasts.