

DIAGNOSTIC TROUBLE CODE CHART

DTC No. (See page)	Detection Item	Trouble Area
B2795 (DI-886)	Unmatched key code	<ul style="list-style-type: none"> • Key • Unregistered key inserted before
B2796 (DI-887)	No communication in immobiliser system	<ul style="list-style-type: none"> • Key • Transponder key coil • Amplifier • Wirehanness • ECM
B2797 (DI-890)	Communication malfunction No.1	<ul style="list-style-type: none"> • Communication contents • Unregistered key inserted before
B2798 (DI-892)	Communication malfunction No.2	<ul style="list-style-type: none"> • Key • Transponder key coil • Amplifier • Wire haness • ECM

HINT:

To reduce the unnecessary exchange of ECM, check that a trouble occurs with the original ECM at the time of exchanging ECM and the trouble will disappear with a new ECM.