

37. Any speaker does not work.

INSPECTION PROCEDURE

1 Is radio operating normally?

Yes

CD auto changer faulty.

No

2 Is hiss noise produced by non-functioning speaker?

Yes

Radio receiver assembly faulty.
Recheck system after repair.

No

3 Does continuity exist in speaker wire harness?

No

Speaker wire harness faulty.

YES

4 Temporarily install another speaker. Function OK?

Yes

Speaker faulty.

No

Radio receiver assembly faulty.
Recheck system after repair.