

Diag. Code 62**TRAC Vehicle Speed Malfunction****— CIRCUIT DESCRIPTION —**

Code No.	Diagnostic Code Detecting Condition	Trouble Area
62	Detection of any of conditions (1) through (3): (1) At vehicle speed of 10 km/h (6 mph) or more, pulses are not input for 5 sec. (2) Momentary interruption of the vehicle speed sensor signal occurs at least 7 times in the time between switching the ignition switch ON and switching it OFF. (3) Abnormal fluctuation of speed sensor signals with the vehicle speed 20 km/h (12 mph) or more.	•ECU

HINT: When Diag. Code Nos. 31–36 are recorded in memory, code No.62 is not recorded.

— DIAGNOSTIC CHART —